

ContiConnect® Yard Reader

Digital Tire Monitoring with Web Portal

- » Yard Reader mounted in the fleet terminal reads sensors in a 65-foot radius*
- Mobile-friendly web portal displays tire data for all vehicles
- » Text and email notifications can alert fleet personnel if an issue is detected
- Ideal for vehicles that return to the fleet yard at least once per week

*Operating radius may be affected by various factors including obstructions.

Properly inflated tires can reduce total tire-related costs by \$600 to \$800 annually per vehicle.

Actual results may vary. According to the Technology & Maintenance Council (TMC) S.2 Tire & Wheel Study Group, improper tire inflation, defined as little as 10 psi low, reduces fuel economy, by about one percent, increases total tire-related costs by approximately \$600 to \$800 annually per tractor-trailer combination, and changes the tire contact patch which affects stopping and acceleration traction and vehicle handling thereby impacting vehicle safety.



((CONNECT

Benefits



Improve Tire Runout



Minimize Irregular Wear



Save Fuel



Save Labor & Maintenance Costs



Reduce Roadside Breakdowns



Improve Safety

System



1 Tire Sensor (One per running wheel)



2 Yard Reader



3 Web Portal & Mobile Alerts

Specs

Short Description	Digital Tire Monitoring with Web Portal
Monitors	All vehicles on the fleet yard (within range of the yard reader)
Data Access	Data is transmitted whenever vehicles are within range of the yard reader. Data is accessible anytime, anywhere in the mobile-friendly ContiConnect Web Portal
Alerts	Text message and email alerts with customizable thresholds and settings
Hardware	Tire sensors, Yard Reader, Hand Held Tool



Powered by Continental's Intelligent Tire

- Accurate, real-time tire pressure and temperature to prevent tire damage and breakdowns
- Sensor warrantied for 5 years* to minimize disruptions to your tire program
- Sensor provides true casing temperature, allowing preventive actions that make your tire last longer
- Avoids valve damage and air leaks by mounting on the inner liner of the tire.

Contact your Continental Representative today!

Need a Representative? Call 1 800 450-3187

Actual results may vary. *See Warranty Policy for details.