

Homologation Certificate Sensor

17340480000/ Rev. 10

June 2025

www.continental-tires.com/products/b2b/services-and-solutions/ContiConnect/downloads/



Model: TIS-21

RX @ 125 kHz; TX @ 433,92 MHz;
Bluetooth® wireless technology @ 2.4 GHz
Tire Sensor (Made in France)
Maximum transmitter power: <10 dBm

Manufacturer address:

Continental Automotive GmbH
Siemensstrasse 12
93055 Regensburg
Germany



Australia (AU)



Belarus (BY)



Brazil (BR)



18013-21-01821

Este equipamento não tem direito à proteção contra interferência prejudicial e não pode causar interferência em sistemas devidamente autorizados.

Canada (CA)

IC: 7812D-TIS21

This device complies with Industry Canada license-exempt RSS standard(s). Operation is subject to the following two conditions:

1. this device may not cause harmful interference, and
2. this device must accept any interference received, including interference that may cause undesired operation.

Le présent appareil est conforme aux CNR d'Industrie Canada applicables aux appareils radio exempts de licence. L'exploitation est autorisée aux deux conditions suivantes:

1. l'appareil ne doit pas produire de brouillage, et
2. l'utilisateur de l'appareil doit accepter tout brouillage radioélectrique subi, même si le brouillage est susceptible d'en compromettre le fonctionnement.

China (CN)

CMIIT: 2022DJ10049

Costa Rica (CR)

01717-SUTEL-DGC-2022

Egypt (EG)

TAC.14022226880.WIR

Ghana (GH)

NCA APPROVED: 7E6-M1-X93-SRD

Liberia (LR)

LTA/COMM-CKM/145/'24

Ivory Coast (CI)

N° 286/DG/DRH/SHO/UHO

Certificate No: 5512042

מספר אישור התאמה מטעם משרד התקשורת
חל איסור לבצע פעולות במכשיר שיש בהן כדי לשנות את
תכונותיו האלחוטיות
של המכשיר, ובכלל זה שינויי תוכנה, החלפת אנטנה
מקורית או הוספת
אפשרות לחיבור לאנטנה חיצונית, בלא קבלת אישור משרד
התקשורת, בשל
החשש להפרעות אלחוטיות

Israel (IL)

Malaysia (MY)



RSQ/78A/0322/S(22-1230)

Mexico (MX)

NYC-2202CT0237



IFT RCPCOTI22-3864



"La operación de este equipo está sujeta a las siguientes dos condiciones:
(1) es posible que este equipo o dispositivo no cause interferencia perjudicial y
(2) este equipo o dispositivo debe aceptar cualquier interferencia, incluyendo la que pueda causar su operación no deseada."

Morocco (MA)



MR00031793ANRT2022

Oman (OM)

OMAN-TRA
D100428

TRA/TA-R/13233/22

Continental Reifen Deutschland GmbH

Registered address: Continental-Plaza 1, 30175 Hannover, Germany

Operating address: Jädekamp 30, D-30419 Hannover, Germany

1 / 2

Philippines (PH)	 NTC Type Accepted No.: ESD-RCE-2229299	United Arabian Emirates (UA)	 
Samoa (WS)	 SMO T-1063/22	FCC ID: KR5TIS-21  Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation. Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.	
Singapore (SG)	Complies with IMDA Standards N0856-22	United States of America (US)	
South Africa (ZA)	 TA-2021/3216 Approved		
South Korea (KR)	 R-C-TAL-TIS-21		
Taiwan (TW)	 CCAM22LP0170T7 根據LP0002低功率射頻器材技術規範 章節3.8.2: 取得審驗證明之低功率射頻器材, 非經核准, 公司、商號或使用者均不得擅自變更頻率、加大功率或變更原設計之特性及功能。 低功率射頻器材之使用不得影響飛航安全及干擾合法通信; 經發現有干擾現象時, 應立即停用, 並改善至無干擾時方得繼續使用。前述合法通信, 指依電信管理法規定作業之無線電通信。低功率射頻器材須忍受合法通信或工業、科學及醫療用電波輻射性電機設備之干擾。	European Union (EU)	
Thailand (TH)	 เครื่องวิทยุคมนาคมนี้ ได้รับยกเว้น ไม่ต้องได้รับใบอนุญาตให้มี ใช้ซึ่งเครื่องวิทยุคมนาคม หรือตั้งสถานีวิทยุคมนาคมตามประกาศ กสทช. เรื่อง เครื่องวิทยุคมนาคม และสถานีวิทยุคมนาคมที่ได้รับยกเว้นไม่ต้องได้รับใบอนุญาต วิทยุคมนาคมตามพระราชบัญญัติวิทยุคมนาคม พ.ศ. 2498  nab. โทรคมนาคม ศูนย์ช่วยเหลือประชาชน Call Center 1200 (Insws)		

Continental Reifen Deutschland GmbH

Registered address: Continental-Plaza 1, 30175 Hannover, Germany

Operating address: Jädekamp 30, D-30419 Hannover, Germany

2 / 2

